BlastTex
Prep. Clean. Ready.
817-600-8452 · blasttex.com

Warehouse Floor Cleaning Checklist: Scrub It or Blast It?

A dirty warehouse floor wears out equipment faster, tracks grime into offices and hides the markings your people rely on. Use this checklist to determine whether your floor needs a scrub, a shot blast or both, and how to prepare for the work.

Signs your floor needs sweeping and scrubbing

- [ ] Visible dust when forklifts pass
- [ ] A gray film or grime visible on the floor
- [ ] Tire marks in the main aisles
- [ ] Lane and walkway lines that are hard to see through the dirt
- [ ] Dirt tracked into offices and break rooms
- [ ] More than about three months since the last machine scrub

Signs scrubbing will not resolve it

Scrubbing cleans the surface. These conditions require shot blasting or other mechanical preparation:

- [ ] Oil stains that have penetrated deep into the concrete
- [ ] Peeling or failed coatings
- [ ] Old lines that must be removed, not just cleaned
- [ ] Adhesives or mastic (only after a clean asbestos test)
- [ ] Tire marks embedded in the surface
- [ ] Ramps and docks where the texture has worn smooth

Before the cleaning crew arrives

- [ ] Aisles and open floor cleared of pallets, product and loose debris
- [ ] Areas that cannot be cleaned that day marked off
- [ ] Work hours agreed; nights and weekends minimize disruption
- [ ] Water fill points and approved wastewater disposal identified under your site rules
- [ ] Signage and reopening planned: floors can be damp immediately after scrubbing

How often

A busy warehouse usually needs a machine scrub about every three months, and busy docks more often. A recurring schedule maintains conditions between cleanings.

Have BlastTex handle it

The Floor Cleaning package: from $1,500 within 50 miles of Hurst, TX, with a ride-on sweeper and ride-on scrubbers for large open floors.

- Sweeping and machine scrubbing, before or after shot blasting, or on its own
- Nights, weekends and zoned work around your operation
- Time-Stamped Photo Report
- **Floor Care Plan:** scheduled cleaning, priced below one-time cleaning
- Free site walk within 50 miles of Hurst

Text floor photos and your square footage to 817-600-8452.

General guidance only. Cleaning may not remove deep stains, embedded marks or permanent discoloration. BlastTex does not test or certify slip resistance or OSHA compliance.

BlastTex · Concrete Surface Preparation Specialists · Family-owned in Hurst, TX · CGL insured · 817-600-8452 · quotes@blasttex.com · blasttex.com